

# PART PROGRAMMING

# INTRODUCTION

A group of commands given to the CNC for operating the machine is called the program.

It consists of:

- Information about part geometry
- Motion statements to move the cutting tool
- Cutting speed
- Feed
- Auxiliary functions such as coolant on and off, spindle direction

## ❑ CNC program structure

There are four basic terms used in CNC programming  
**Character -> Word -> Block -> Program**

- Character is the smallest unit of CNC program. It can have Digit / Letter / Symbol.
- Word is a combination of alpha-numerical characters. This creates a single instruction to the CNC machine. Each word begins with a capital letter, followed by a numeral. These are used to represent axes positions, federate, speed, preparatory commands, and miscellaneous functions.
- A program block may contain multiple words, sequenced in a logical order of processing.
- The program comprises of multiple lines of instructions, 'blocks' which will be executed by the machine control unit (MCU).

# FIXED ZERO v/s FLOATING ZERO

## Fixed zero:

- Origin is always located at some position on M/C table (usually at south west corner/Lower left-hand) of the tables & all tool location are defined W.R.T. this zero

## Floating Zero:

- Very common with CNC M/C used now a days.
- Operator sets zero point at any convenient position on M/C table.
- The Coordinate system is known as work coordinate system (WCS)



## Modal and Non modal commands

- Commands issued in the NC program may stay in **effect indefinitely** (until they explicitly cancelled or changed by some other command), or they may be effective for only the one time that they are issued.
- The former are referred as **Modal commands**. Examples include feed rate selection and coolant selection.
- Commands that are **effective only when issued** and whose effects are lost for subsequent commands are referred to as **non-modal commands**.
- A dwell command, which instructs the tool to remain in a given configuration for a given amount of time, is an example of a non-modal command.

# Structure of an NC part program

- An NC part program is made up of a series of commands that are input into the MCU in a serial manner.
- The MCU interprets these commands and generates the necessary signals to each of the drive units of the machine to accomplish the required action.
- The NC program is required to have a particular structure that the controller can understand and it must follow a specific syntax.
- Commands are inputs into the controller in units called blocks or statements.
- Each block is made up of one or more machine commands.

- In general, several commands are grouped together to accomplish a specific machining operation, hence the use of a block of information for each operation.
- Each command gives a specific element of control data, such as dimension or a feed rate. Each command within a block is also called a word.
- The way in which words are arranged within the block is called block format.
- Three different block formats are commonly used, (Fixed sequential format, Tab sequential format and Word address format)

## Word Sequential Format : Used on virtually all modern controllers.

```
N50 G00 X50 Y25 Z0 F0  
N60 G01 Z-1 F50 M08  
N70 Z0 M09
```

- With this type of format, each type of word is assigned as address that is identified by a letter code within the part program.
- Thus the letter code specifies the type of word that follows and then its associated numeric data is given.
- For example, the code T represents a tool number. Thus a word of the form T01 would represent tool number 1.
- Theoretically, with this approach, the words in a given block can be entered in any sequence and the controller should be able to interpret them correctly.

- With the word address format only the needed words for a given operation have to be included within the block.
- The command to which the particular numeric data applies is identified by the preceding address code.
- Word format has the advantage of having more than one particular command in one block something that would be impossible in the other two formats.

## COMMONLY USED WORD ADDRESSES

- **N-CODE**: Sequence number, used to identify each block with in an NC program and provides a means by which NC commands may be rapidly located. It is program line number. It is a good practice to increment each block number by 5 to 10 to allow additional blocks to be inserted if future changes are required.
- **G-CODE**: Preparatory Word, used as a communication device to prepare the MCU. The G-code indicates that a given control function such as G01, linear interpolation, is to be requested.
- **X, Y & Z-CODES**: Coordinates. These give the coordinate positions of the tool.

- **F-CODE**: Feed rate. The F code specifies the feed in the machining operation.
- **S-CODE**: Spindle speed. The S code specifies the cutting speed of the machining process.
- **T-CODE**: Tool selection. The T code specifies which tool is to be used in a specific operation.
- **M-CODE**: Miscellaneous function. The M code is used to designate a particular mode of operation for an NC machine tool.
- **I, J & K-CODES**: They specify the centre of arc coordinates from starting.

Sequence and format of words:

N3 G2 X+1.4 Y+1.4 Z+1.4 I2.0 J2.0 K2.0 F5 S4 T4 M2

sequence no

preparatory function

destination coordinates

dist to center of circle

feed rate

spindle speed

tool

Other function



G00	Rapid Linear Positioning	G55	Work Coordinate System 2 Selection
G01	Linear Feed Interpolation	G56	Work Coordinate System 3 Selection
G02	CW Circular Interpolation	G57	Work Coordinate System 4 Selection
G03	CCW Circular Interpolation	G58	Work Coordinate System 5 Selection
G04	Dwell	G59	Work Coordinate System 6 Selection
G07	Imaginary Axis Designation	G60	Single Direction Positioning
G09	Exact Stop	G61	Exact Stop Mode
G10	Offset Value Setting	G64	Cutting Mode
G17	XY Plane Selection	G65	Custom Macro Simple Call
G18	ZX Plane Selection	G66	Custom Macro Modal Call
G19	YZ plane Selection	G67	Custom Macro Modal Call Cancel
G20	Input In Inches	G68	Coordinate System Rotation On
G21	Input In Millimeters	G69	Coordinate System Rotation Off
G22	Stored Stroke Limit On	G73	Peck Drilling Cycle
G23	Stored Stroke Limit Off	G74	Counter Tapping Cycle
G27	Reference Point Return Check	G76	Fine Boring
G28	Return To Reference Point	G80	Canned Cycle Cancel
G29	Return From Reference Point	G81	Drilling Cycle, Spot Boring
G30	Return To 2nd, 3rd and 4th Ref. Point	G82	Drilling Cycle, Counter Boring
G31	Skip Cutting	G83	Peck Drilling Cycle
G33	Thread Cutting	G84	Tapping Cycle
G40	Cutter Compensation Cancel	G85	Boring Cycle
G41	Cutter Compensation Left	G86	Boring Cycle
G42	Cutter Compensation Right	G87	Back Boring Cycle
G43	Tool Length Compensation + Direction	G88	Boring Cycle
G44	Tool Length Compensation - Direction	G89	Boring Cycle
G45	Tool Offset Increase	G90	Absolute Programming
G46	Tool Offset Double	G91	Incremental Programming
G47	Tool Offset Double Increase	G92	Programming Of Absolute Zero
G48	Tool Offset Double Decrease	G94	Feed Per Minute
G49	Tool Length Compensation Cancel	G95	Feed Per Revolution
G50	Scaling Off	G96	Constant Surface Speed Control
G51	Scaling On	G97	Constant Surface Speed Control Cancel
G52	Local Coordinate System Setting	G98	Return To Initial Point In Canned Cycles
G54	Work Coordinate System 1 Selection	G99	Return To R Point In Canned Cycles

## List of M codes

M codes vary from machine to machine depending on the functions available on it. They are decided by the manufacturer of the machine. The M codes listed below are the common ones.


<b>M-codes</b>	<b>Function</b>
M00	Optional program stop automatic
M01	Optional program stop request
M02	Program end
M03	Spindle ON clock wise (CW)
M04	Spindle ON counter clock wise (CCW)
M05	Spindle stop
M06	Tool change
M07	Mist coolant ON (coolant 1 ON)
M08	Flood coolant ON (coolant 2 ON)
M09	Coolant OFF
M30	End of program, Reset to start
M98	Sub program call
M99	Sub program end

## G00 Rapid traverse

When the tool being positioned at a point preparatory to a cutting motion, to save time it is moved along a straight line at Rapid traverse, at a fixed traverse rate which is pre-programmed into the machine's control system.

Typical rapid traverse rates are 10 to 25 m /min., but can be as high as 80 m/min.


Syntax: N010 [G90/G91] G00 X10 Y10 Z5



## **G01 Linear interpolation** (feed traverse)

The tool moves along a straight line in one or two axis simultaneously at a programmed linear speed, the feed rate.

Syntax: N010[G90/G91] G01 X10 Y10 Z5 F25



## G02/G03 Circular interpolation

Format


N\_\_ G02/03 X\_\_ Y\_\_Z\_\_ I\_\_ J\_\_K\_\_ F\_\_ using the arc center

or


N\_\_ G02/03 X\_\_ Y\_\_Z\_\_ R\_\_ F\_\_ using the arc radius

Arc center

The arc center is specified by addresses I, J and K. I, J and K are the X, Y and Z co-ordinates of the arc center with reference to the arc start point.




G02 moves along a CW arc



G03 moves along a CCW arc

## G90 ABSOLUTE POSITION COMMAND

- When using a G90 absolute position command, each dimension or move is referenced from a fixed point, known as ABSOLUTE ZERO (part zero).
- Absolute zero is usually set at the corner edge of a part, or at the center of a square or round part, or an existing bore. ABSOLUTE ZERO is where the dimensions of a part program are defined from.
- Absolute dimensions are referenced from a known point on the part, and can be any point the operator chooses, such as the upper-left corner, center of a round part, or an existing bore.




Syntax: N.. G90 X.. Y.. Z.. A.. B.. C..



## G91 INCREMENTAL POSITION COMMAND

- This code is modal and changes the way axis motion commands are interpreted. G91 makes all subsequent commands incremental. Zero point shifts with the new position.


Syntax: N.. G91 X.. Y.. Z.. A.. B.. C..



# G 17 G18 G19 : PLANE SELECTION


**G 17** : XY plane selection

Syntax: N.. G17




**G 18** : ZX plane selection

Syntax: N.. G18




**G 19** : ZY plane selection

Syntax: N.. G19




Syntax: N020 G17 G75 F6.0 S300 T1001 M08






G 70 Inch data input

G 71 Metric data input



Syntax : N010 G70 G90 G94 G97 M04


# Manual Part Programming Example



Tool size = 0.25 inch,  
Feed rate = 6 inch per minute,  
Cutting speed = 300 rpm,  
Tool start position: 2.0, 2.0  
Programming in inches

Motion of tool:  
 $p0 \rightarrow p1 \rightarrow p2 \rightarrow p3 \rightarrow p4 \rightarrow p5 \rightarrow p1 \rightarrow p0$

# 1. Set up the programming parameters



Programming in inches

Use absolute coordinates


Feed in ipm

N010 G70 G90 G94 G97 M04

Spindle speed in rpm

Spindle CCW

## 2. Set up the machining conditions



Machine moves in XY-plane

Use full-circle interpolation

Feed rate


Spindle speed

`N020 G17 G75 F6.0 S300 T1001 M08`


Tool no.

Flood coolant ON

### 3. Move tool from p0 to p1 in straight line



## 4. Cut profile from p1 to p2



Linear interpolation

target coordinates

N040 G01 X3.875 Y9.125




or


N040 G01 Y9.125

X-coordinate does not change → no need to program it

## 5. Cut profile from p2 to p3



## 6. Cut along circle from p3 to p4



circular interpolation, CCW motion

target coordinates


N060 G03 X7.366 Y9.125 I6.5 J9.0

coordinates of center of circle


N060 G03 X7.366 Y9.125 I0.866 J-0.125




## 7. Cut from p4 to p5



## 8. Cut from p5 to p1




## 9. Return to home position, stop program



## 10. Complete RS-274 program

```
N010 G70 G90 G94 G97 M04  
N020 G17 G75 F6.0 S300 T1001 M08  
N030 G01 X3.875 Y3.698  
N040 G01 X3.875 Y9.125  
N050 G01 X5.634 Y9.125  
N060 G03 X7.366 Y9.125 I0.866 J-0.125  
N070 G01 X9.302  
N080 G01 X3.875 Y3.698  
N090 G01 X2.0 Y2.0 M30
```

## Simple G Code Example CNC Lathe



# PART PROGRAM

N5 M12

N10 T0101

N15 G0 X100 Z50

N20 M3 S600

N25 M8

N30 G1 X50 Z0 F600

N40 Y-30 F200

N50 X80 Y-20 F150

N60 G0 X100 Z50

N70 T0100

N80 M5

N90 M9

N100 M13

N110 M30

## **Code Explanation**

N5 Clamping workpiece

N10 Changing No.1 tool and executing its offset

N15 Rapidly positioning to A point

N20 Starting the spindle with 600 r/min

N25 Cooling ON

N30 Approaching B point with 600mm/min

N40 Cutting from B point to C point

N50 Cutting from C point to D point

N60 Rapidly retracting to A point

N70 Cancelling the tool offset


N80 Stopping the spindle

N90 Cooling OFF

N100 Releasing workpiece

N110 End of program, spindle stopping and Cooling OFF

## CNC MILLING EXAMPLE





N5 G90 G71

N10 T1 M6

N15 G92 X-100 Y86 Z95

N20 G0 X0 Y0 S2500 M3

N25 Z12.5

N30 G1 Z-12.5 F150

N35 X-20 Y30

N40 G2 X10 Y100 R80

N45 G1 X140 Y60

N50 G2 X150 Y0 R50

N55 G1 X0 Y0

N60 G0 Z12.5

N65 G91 G28 Z0 M5

N70 G91 G28 X0 Y0

N75 M30

## CODE EXPLANATION

N5 absolute positioning, metric unit

N10 tool change to T1

N15 define work zero point at A

N20 rapid traverse to A, spindle on (2500 RPM, CW)

N25 rapid plunge to 12.5 mm above Z0

N30 feed to Z-12.5, feed rate 150 MPM

N35 cut line AB to B

N40 cut arc BC to C

N45 cut line CD to D

N50 cut arc DE to E

N55 cut line EA to A


N60 rapid retract to Z12.5

N65 reference point return in Z direction, spindle off

N70 reference point return in X and Y directions

N75 end of program

## SAMPLE PROGRAM ON DRILLING



N1 T16 M06

N2 G90 G54 G00 X0.5 Y-0.5

N3 S1450 M03

N4 G43 H16 Z1. M08

N5 G81 G99 Z-0.375 R0.1 F9.

N6 X1.5

N7 Y-1.5

N8 X0.5

N9 G80 G00 Z1. M09

N10 G53 G49 Z0. M05

N11 M30

## CODE EXPLANATION

N1- Tool change (M06) to tool no.16

N2- Tool rapidly moves (G00) to first drilling position X0.5 Y-0.5 while taking into account Zero-offset-no. 1 (G54)

N3- Drill starts rotating clockwise (M03) with 1450 rpm (S1450).

N4- Drill takes depth Z1. taking into account tool length compensation (G43 H16), coolant is turned on (M08).

N5- Drilling cycle (G81) parameters, drill depth (Z) and cutting feed (F) are given, with this command first drill is made at current position (X0.5 Y-0.5).

N6- As drilling cycle continues it's work with every axis movement so next drill is done at X1.5

N7- Third drilling hole at Y-1.5

N8- Fourth drill at X0.5

N9- Drilling cycle is cancelled (G80), Coolant is turned off (M09).


N10- Taking Machine-coordinate-system (G53) into account the drill is taken to Z0 position. Tool length compensation is cancelled (G49), cutter rotation is stopped (M05).

N11- CNC part-program is ended.

# Typical PROGRAMMING - TURNING OPERATIONS

Write a part program for turning operations being carried out on a CNC turning center. Let us take an exercise:

Figure shows the final profile to be generated on a bar stock by using a CNC turning center. After studying the required part geometry and features, the main program can be written as follows.




**Figure A component to be turned.**


Block 1		%
2		O0004
3	N10	G21
4	N20	G40 G90
5	N30	G54 X... Z...
6	N40	T0100 M42
7	N50	G96 S450 M03
8	N60	G00 G41 X72 Z0 T0101 M08
9	N70	G01 X0
10	N80	G00 Z5
11	N90	G42 X72
12	N100	G71 U1 R3
13	N110	G71 P120 Q190 U1 W1 F0.05
14	N120	G00 X0
15	N130	G01 Z0
16	N140	G03 X20 Z-20
17	N150	G01 Z-45
18	N160	X40 Z-80
19	N170	Z-105
20	N180	G02 X70 Z-120
21	N190	G01 X75
22	N200	G00 X100 Z20
23	N210	G70 P120 Q190 F0.03
24	N220	G00 G40 X100 Z20 T0100
25	N230	M09
26	N240	M30
27		%



## Module 3




# **Rapid Prototyping & Rapid Tooling**



**Corso di Sistemi integrati di Produzione A.A.2004-05**  
**Prof. G. A. Berti**

# Rapid Prototyping achievements


- Reduction in prototyping times (from weeks to days)
- Reduction in prototyping costs (from thousands to hundreds \$)
- Increase of the possible design iterations (from 2-3 to 8-9)
- Increase of possible form, fit, function tests





**Shorter design cycle**

**Reduced Time-to-Market**



# Rapid Prototyping





Computer model



Mechanical model



Visual model



Mechanical functional model





Production product


# Rapid Prototyping Market

## 2001

- 3,55 Millions of models produced worldwide
- 400 Service providers
- 8000 Machines sold since 1993



Source: Wohlers Associates, Inc.



# Useful Conditions for RP

- Single unique item or small number of copies needed
- Shape of object is in computer form
- Shape is too complex to be economically generated using conventional methods

# Rapid Prototyping Technologies

- Six basic commercial technologies:

StereoLithography (SL)

Laminated Object Manufacturing (LOM)





Selective Laser Sintering (SLS)

Fused Deposition Modeling (FDM)

Solid Ground Curing (SGC)

Inkjet technologies (3D Plotting, MJM, 3DP..)



# Rapid Prototyping Examples



Examples of parts made by rapid prototyping processes.



# Rapid Prototyping Examples / 2



# Characteristics of Rapid Prototyping Technologies

TABLE 19.1

Supply phase	Process	Layer creation technique	Phase change type	Materials
Liquid	Stereolithography	Liquid layer curing	Photopolymerization	Photopolymers (acrylates, epoxies, colorable resins, filled resins)
	Solid-based curing	Liquid layer curing and milling	Photopolymerization	Photopolymers
	Fused-deposition modeling	Extrusion of melted polymer	Solidification by cooling	Polymers (ABS, polyacrylate, etc.), wax, metals and ceramics with binder.
	Ballistic-particle manufacturing	Droplet deposition	Solidification by cooling	Polymers, wax
Powder	Three-dimensional printing	Layer of powder and binder droplet deposition	No phase change	Ceramic, polymer and metal powders with binder.
	Selective laser sintering	Layer of powder	Laser driven sintering melting and solidification	Polymers, metals with binder, metals, ceramics and sand with binder.
Solid	Laminated-object manufacturing	Deposition of sheet material	No phase change	Paper, polymers.


### The Most Important Commercial Rapid Prototyping Technologies at a Glance

Technology >>	<u>Stereo-lithography</u>	<u>Stereo-lithography</u>	<u>Wide Area Thermal Inkjet</u>	<u>Selective Laser Sintering</u>	<u>Fused Deposition Modeling</u>	<u>Single Jet Inkjet</u>	<u>Three Dimensional Printing</u>	<u>Laminated Object Manufacturing</u>
Acronym > >	SLA	SLA	MJM	SLS	FDM	MM	3DP	LOM
Representative Vendor >>	Sony	3D Systems			Stratasys	Solidscape	Z Corp.	Cubic Technologies
General Qualitative Features								
Maximum Part Size (inches)	39 x 31 x 20	20 x 20 x 24	10 x 8 x 8	15 x 13 x 18	24 x 20 x 24	12 x 6 x 9	20 x 24 x 16	32 x 22 x 20
Speed	very good  (uses dual beams for approx. 2X speed-up)	average	good	average to fair	poor	poor	excellent	good
Accuracy	very good	very good	good	good	fair	excellent	fair	fair
Surface Finish	very good	very good	fair	fair	fair	excellent	fair	fair to poor (depending on application)
Strengths	very large part size, accuracy speed	large part size, accuracy	office OK	accuracy, materials,	office OK price, materials	accuracy, finish, office OK	speed, office OK, price, color, price	large part size, good for large castings, material cost
Weaknesses	post processing, messy liquids	post processing, messy liquids	size and weight, fragile parts, limited materials, part size	size and weight, system price, surface finish	speed	speed, limited materials, part size	limited materials, fragile parts, finish	part stability, smoke finish and accuracy


# Stereolithography SL

- 3D Systems, Valencia, CA
- patent 1986, beginning of RP
- photopolymerization using UV laser
- accuracy 0.025 mm
- epoxies, acrylates

# Stereolithography SL




# Stereolithography




Schematic illustration of the stereolithography process. Source: Ultra Violet Products, Inc.

# Stereolithography SL







# Stereolithography Machines









# Stereolithography Process



# SL Applications




# SL Applications




# Stereo-lithography

The computational steps in producing a stereolithography file.


- a) Three-dimensional description of part.
- b) The part is divided into slices (only one in 10 is shown).
- c) Support material is planned.
- d) A set of tool directions is determined to manufacture each slice.




(a)



(b)



(c)




(d)

# RP Sequence


- CAD solid model
- '.STL' file
- Slicing the file
- Final build file
- Fabrication of part
- Post processing

# CAD Solid Model

- Solid model or closed surface model required



# ‘.STL’ File




- Software generates a tessellated object description
- File consists of the X, Y, Z coordinates of the three vertices of each surface triangle, with an index to describe the orientation of the surface normal
- Support generation to hold overhung surfaces during build

# Slicing the File

- Series of closely spaced horizontal planes are mathematically passed through the .stl file
- Generate a '.sli' file : a series of closely spaced 2D cross-sections of the 3D object
- Typical Z thickness 0.006" (0.150 mm)
- Other Parameters chosen =fn(RP technology)




# Common Support Structures



- (a) A part with a protruding section which requires support material.  
(b) Common support structures used in rapid-prototyping machines.

Source: P.F. Jacobs, *Rapid Prototyping & Manufacturing: Fundamentals of Stereolithography*. Society of Manufacturing Engineers, 1992.

# Final Build File





Part sliced

Supports sliced

RP technology parameters set (layer thickness, scan speed,...)

Send file to RP machine

# Fabrication of Part



**Models built on stereolithography apparatus.  
Part and supports shown attached to platform.**

# Post-processing

Removal of part from platform

Removal of supports from part


Cleaning of part (wiping, rinsing, ... )

Finishing part (sanding, polishing, ... )


# Laminated Object Manufacturing LOM

- Cubic Technologies, Carson, CA (former Helisys)
- patent 1985
- cross-sectional cutouts fused together
- accuracy 0.076 mm
- paper, plastic



# Laminated Object Manufacturing LOM



# Laminated Object Manufacturing LOM



# Laminated-Object Manufacturing







- (a) Schematic illustration of the laminated-object-manufacturing process. *Source:* Helysis, Inc.
- (b) Crankshaft-part example made by LOM. *Source:* After L. Wood.



# Helisys LOM 1015




# LOM Applications




# Selective Laser Sintering SLS

- 3D Systems, Valencia, CA (former DTM)
- patent 1989, Carl Deckard's master thesis
- fusing polymeric powders with CO<sub>2</sub> laser
- accuracy 0.040 mm
- polycarbonate, nylon, wax, glass-filled nylon, powder coated metals or ceramics



# Selective Laser Sintering




## *How the SLS System Works*



# Selective Laser Sintering SLS




# Selective Laser Sintering








Schematic illustration of the selective laser sintering process. *Source:* After C. Deckard and P.F. McClure.

# Selective Laser Sintering



# SLS Applications






# Fused Deposition Modeling




## FDM

- Stratasys, Eden Prairie, MN
- patent 1992
- robotically guided fiber extrusion
- accuracy 0.127 mm
- casting and machinable waxes, polyolefin, ABS, PC


# Fused Deposition Modeling FDM



# Fused Deposition Modeling FDM




# Fused-Deposition-Modeling





(a) Schematic illustration of the fused-deposition-modeling process.

(b) The FDM 5000, a fused-deposition-modeling-machine. *Source:* Courtesy of Stratysis, Inc.

# FDM Machines




# FDM Applications



# Solid-Base Curing SBC

- Cubital, Troy, MI (Failed 2000)
- patent 1991
- photopolymerization using UV light passing through a mask
- accuracy 0.510 mm
- Photopolymers


# Solid-Base Curing



Schematic illustration of the solid-base-curing process. Source: After M. Burns, *Automated Fabrication*, Prentice Hall, 1993.




# Solid-Base Curing




# 3D Plotting

- Solidscape Inc., Merrimack, NH
- Inkjet technology
- Dual heads deposit part material (thermoplastic) and support material (wax)
- Accuracy 0.025 mm (layers 0.013 mm)
- Thermoplastic (build)  
Wax, fatty esters (support)




# 3D Plotting



# 3D Plotting



# 3D Plotting Applications




# Multi-jet Modelling


## MJM

- Accelerated Tech., 3D Systems, Solidimension Ltd
- Inkjet technology
- Multiple heads deposit support material and part material cured immediately by UV light
- Accuracy 0.020 mm
- Photopolymers

# Multi-jet Modelling MJM



# MJM Applications






# 3D Printing 3DP



- Z Corporation, Burlington, MA
- Printing head deposits binder solution on build powder
- Accuracy 0.076 mm
- Waxes, acrylates, epoxies

# 3D Printing





Schematic illustration of the three-dimensional-printing process. *Source: After E. Sachs and M. Cima.*


# 3D Printing



# 3D Printing Applications




# Investment Casting



Manufacturing steps for investment casting that uses rapid-prototyped wax parts as blanks. This approach uses a flask for the investment, but a shell method can also be used. *Source: 3D Systems, Inc.*


# **Manufacturing**

## **Example: Investment Casting**




- **Wax pattern build from Stratasys multi-jet droplet technique**
- **Pattern used in investment casting to fabricate metal ring**
- **Allows for design modifications and quick turnaround of metal band**


# Sand Casting Using Rapid-Prototyped Patterns




1. Produce pattern using rapid prototyping process.



2. Produce sand core from mold produced through rapid prototyping.



3. Place drag half of pattern on mold board in drag half of flask




4. Preparing drag half of mold.


Manufacturing steps in sand casting that uses rapid-prototyped patterns.

Source: 3D Systems, Inc.



# Sand Casting (continued)




5. Roll drag over, place cope half of pattern and flask.  
Note: sprue and risers are standard inserts



6. Preparing cope half of mold;  
this step must be repeated for  
each half of the mold




7. Separate flask — remove all patterns.  
Place core in place, close flask.



8. Flask closed and clamped,  
ready for pouring of molten  
metal.



# Rapid Tooling



Rapid tooling for a rear-wiper-motor cover

# Benefits to RP Technologies

Visualization, verification, iteration, and design optimization

Communication tool for simultaneous engineering

Form-fit-function tests

Marketing studies of consumer preferences

Metal prototypes fabricated from polymer parts

Tooling fabricated from polymer parts

# Conclusions

- Rapid prototyping is a new tool, which used appropriately ...
  - allows the manufacturing enterprise to run smoother
  - increases throughput and product quality
- New uses and applications are discovered everyday
- Future areas include new materials directly deposited (metals, ceramics)